



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor

Robert L. Morgan
Executive Director

Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340 telephone
(801) 359-3940 fax
(801) 538-7223 TTY
www.nr.utah.gov

February 26, 2003

TO: Minerals File

FROM: Doug Jensen, Reclamation Engineer *DJensen*

RE: Site Inspection, Ron Stout, Red Sandstone Quarry, M/053/073, Washington County, Utah

Date of Inspection: February 3, 2003
Time of Inspection: 6:45 p.m.
Conditions: Cool, Cloudy
Participants: Doug Jensen, DOGM

Purpose of Inspection:

This inspection was to check the site for changes since my last inspection.

Getting to the site:

Please refer to my July 17, 2002 inspection memo.

Observations:

There was no one at the site when I arrived. There were two loaders, a drill and a dozer parked on the Stout Property. On an adjacent property, which Mr. Stout had indicated did not belong to him, there has been quite a bit of activity. This area had been blasted and a trackhoe, which I believe had been operating on the Red Sandstone permit area, was parked on the blasted pile.

The small portable crusher remains on Mr. Stout's area and there are several product piles located on the site.

The material within the Red Sandstone Quarry appears to be all bedrock. I could not find any evidence of any alluvial material remaining within the operations area.

I made a check of the area where Mr. Stout had indicated that they had been placing road base for a new road. This area is located ~1/2 mile east of the quarry. There has not been any apparent work done in this area since my July 17, 2002 site inspection.

Conclusions and Recommendations:

I will continue to monitor the site and will contact Mr. Stratton to ascertain whether he is also removing material from the adjacent site.

jb

O:\M053-Washington\M053073-redsandstone\inspections\ins02032003.doc